

Revision Date: 12/18/2024

Subject: E470 Error Code

Models: ECO, FJM, RAC, CAC

Title: Outdoor Unit EEPROM Read or Write Error

Troubleshooting Steps

1. Verify the EEPROM is inserted correctly onto the Main PCB.
2. If replacing Main PCB, ensure original EEPROM is installed on replacement Main PCB.
3. When system power is restored, if the same error returns, replace EEPROM with a Pre-programmed EEPROM chip.



Align the half circles when putting the EEPROM in

